

PPE Checklist

Contact and Droplet Precautions

Steps for putting on PPE			Steps for taking off PPE		
1		Clean hands	1		Gloves
2		Gown	2		Clean hands
3		Mask with visor or mask* and eye protection	3		Gown
4		Gloves	4		Clean hands
			5		Mask with visor or mask and eye protection
			6		Hand sanitizer or soap and water

*For [Aerosol-generating medical procedures](#) use fit-tested N95 respirator instead of surgical/procedure mask